

# BMTA Annual Walk-thru Report

Section(s) Evaluated: \_\_\_\_\_ Unicoi Gap to TN 68 – Section 14b-c 4.7 miles \_\_\_\_\_

Direction walked (circle one):    -northbound-                -southbound-

Evaluator(s) Name(s) \_\_\_\_\_ Al Rymer and Cherokee Hiking Club \_\_\_\_\_

Evaluation Date: \_\_\_\_\_ 5/18/09 \_\_\_\_\_

Work hours: \_\_2.5 hrs\_\_\_\_                Travel Hours: \_\_\_\_2 hrs\_\_\_\_

Reporting Evaluator's phone #: \_\_\_\_\_

**Please see the reverse side (or below, if online) for evaluator suggestions and for a quick review of BMTA standards to use as a basis for your evaluation.**

Overall assessments: Rate each category 1-5, with 3 being “ok” and 5 being “excellent.”

Treadway (1-5) \_\_3\_\_\_\_    Motorcycles have worn a deep trench in sections

Corridor Clearance (1-5) \_\_5\_\_\_\_

Blazes, Signs and Trailmarkers (1-5) \_\_5\_\_\_\_

Overall rating for the section (1-5) \_\_4.65\_\_\_\_

**Comments on problem areas (be as specific as you can on location):**

We parked the shuttle on TN68 at the wrong place because there is not a sign of any kind. One tree was blazed but unless you come from the opposite direction you would never see it. Need sign along the road.